


MOS TECHNOLOGY, INC.

VALLEY FORGE CORPORATE CENTER (215) 666-7950
950 RITTENHOUSE ROAD, NORRISTOWN, PA. 19401



March 1, 1976

Dear KIM-1 Customer:

The attached Errata Sheet #3 should be used to eliminate additional errors discovered in the documentation for your KIM-1 System. Please mark your KIM-1 User Manual to reflect these changes.

Thank you,

MOS Technology, Inc.
KIM-1 Customer Support

ea

KIM-1
Errata Sheet #3

- Page 18 - In Fig. 2.4:
Remark Pin A-R (Printer Return) to be A-S
Remark Pin A-S (Keyboard Return) to be A-R
- Page 30 - On left side of Fig. 3-7, remark to show "Peripheral Bus to 6530-002" (not 6530-003).
- Change TTY data pin from PB7 to PA7
- Page 39 - Change last two entries in Fig. 3.13 to show:
17F7 as EAL (not 17F8)
17F8 as EAH (not 17F9)
- Page B-1 - CR5 is shown reversed on the layout diagram. The cathode of CR5 is to your left when correctly installed.
- Page D-1 - Remove decimal point before + 5v, 1.2A designation (Not +.5v; 1.2A)
- Resistor in +12 supply should read 1 Ω (not .47 Ω).
- Page E-3 - In the waveform for the "1 Bit", in the middle group, change to show 6 pulses (not 9).
- Page C-2 - in the fourth line from the top, change to Pin A-P (not A-B).
- Page 74 - the schematic of Fig. 6.2 should be changed to show a more commonly available non-inverting line receiver. Also, the connections to the decoders (74145) should be corrected as shown in the diagram on the following page:

